

# MATERIAL SAFETY DATA SHEET As of: January 2, 2015

Micro 100 Tool Corporation 1410 E Pine Ave, Meridian, ID, 83642 800-635-3080

Page **1** of **3** 

CHEMICAL NAME: Cemented Carbide Product with Cobalt binder

TRADE NAME & SYNONYMS: MICRO 100 SUPER CARBIDE CHEMICAL FAMILY: Refractory Metal Carbide

MOLECULAR WEIGHT: N/A

## PHYSICAL DATA

**Appearance and Odor:** Dark Gray Metal/No Odor **Specific Gravity (H<sub>2</sub>O = 1):** 11.0 to 15.5

Boiling Point:N/APercent Volatile by Volume:0Vapor Pressure (mm Hg):N/AEvaporation Rate:N/AVapor Density (Air = 1):N/AHow Best Monitored:Air Sample

**Solubility in Water:** Insoluble

## HAZARDOUS INGREDIENTS

	Percent by	OSHA	ACGIH
Tungsten (limits for Tungsten dust)	67 – 97%		$5 \text{ mg/m}^3$
Cobalt	3 – 30%	$0.1 \text{ mg/m}^3$	$0.1 \text{ mg/m}^3$
Tantalum (limits for Tantalum dust)	0 - 20%	$5 \text{ mg/m}^3$	$5 \text{ mg/m}^3$
Molybdenum (limits for Molybdenum dust)	0 - 5%	$15 \text{ mg/m}^3$	$10 \text{ mg/m}^3$
Material	Weight	PEL	TLV

## **HEALTH HAZARD DATA**

which can be inhaled, swallowed, or come in contact with the skin or eyes.

**Effects of Overexposure:** Dust from grinding can cause irritation of the nose and throat. Some studies associate periodic inhalation of this respirable dust with the potential for transient respiratory reaction in Cobalt hyper sensitized

of this respirable dust with the potential for transient respiratory reaction in Cobalt hyper sensitized individuals and prolonged excessive inhalation or respirable dust or mist with transient, permanent, or

fatal respiratory disease. Adverse reactions are purportedly due to the Cobalt ingredient.

**Skin Contact** Can cause irritation or transient allergic skin rash in Cobalt hyper sensitized individuals.

**Eye Contact** Can cause pain or irritation.

**Ingestion** Reports outside the industry suggest that ingestion of significant amounts of Cobalt has the potential for

causing blood, heart, and other organ problems.

**Emergency and First Aid** 

**Procedures:** Applicable for dusts or mists.

**Inhalation** If symptoms of pulmonary involvement develop (coughing, wheezing, shortness of breath, etc.) remove

from exposure and seek medical attention.

**Skin Contact** If irritation or rash occurs, thoroughly wash affected area with soap and water and isolate from exposure.

If irritation or rash persists, seek medical attention.



# MATERIAL SAFETY DATA SHEET As of: January 2, 2015

Micro 100 Tool Corporation 1410 E Pine Ave, Meridian, ID, 83642 800-635-3080

Page **2** of **3** 

**Eye Contact** If irritation occurs, flush copious amounts of water. If irritation persists, seek medical attention.

**Ingestion** If substantial quantities are swallowed, dilute with a large amount of water, induce vomiting, and seek

medical attention.

## Carcinogenic Assessment (NTP Annual Report, IARC Monographs, others):

None of the components of this material have been identified as known or suspected carcinogens by NTP, IARC, or OSHA.

## FIRE AND EXPLOSION HAZARD DATA

Flash Point: N/A Test Method Used: -- Flammable Limits: N/A LEL: -- UEL: --

Hard Cemented Tungsten Carbide Product is not a fire hazard. Dusts generated in grinding operations may ignite if allowed to accumulate and subjected to an ignition source.

Extinguishing Media: For powder fires use dry sand, dry dolomite, ABC type fire extinguisher, or flood with water.

**Special Fire Fighting Procedures:** For a powder fire contained in a small area, use a respirator approved for toxic dusts and fumes. For a large fire, fire fighters should use self-contained breathing apparatus.

**Unusual Fire and Explosion Hazards:** Dusts may present a fire or explosion hazard under rare favoring conditions of particle size, dispersion, and strong ignition source. However, this is not expected to be a problem under normal handling conditions.

#### REACTIVITY DATA

Stability: Conditions to Avoid: N/A

Unstable

Stable X

**Incompatibility:** Contact of dust with strong oxidizers may

Materials to Avoid: Strong acids.

cause fire or explosions.

Hazardous Decomposition Products: None Conditions to Avoid: N/A

**Hazardous Polymerization:** 

**May Occur** 

Will Not Occur: X

## SPILL OR LEAK PROCEDURES

## Steps to be Taken in Case Material is Released or Spilled:

Ventilate area of spill. Clean up methods which avoid dust generation such as vacuum (with appropriate filter to prevent airborne dust levels which exceed the PEL or TLV), wet mop, or wet clean-up. If airborne dust is generated, use an appropriate NIOSH approved respirator.

## **Waste Disposal Method:**

Dispose of in accordance with appropriate government regulations. May be sold as scrap for reclaim.



# MATERIAL SAFETY DATA SHEET As of: January 2, 2015

Micro 100 Tool Corporation 1410 E Pine Ave, Meridian, ID, 83642 800-635-3080

Page 3 of 3

## SPECIAL PROTECTION INFORMATION

## **Respiratory Protection:**

Use an appropriate NIOSH approved respirator if airborne dust concentrations exceed the appropriate PEL or TLV. All appropriate requirements set forth in 29 CFR 1910.134 should be met.

#### Ventilation:

Use local exhaust ventilation which is adequate to limit personal exposure to airborne dust to levels which do not exceed the PEL or TLV. If such equipment is not available use respirators as specified above.

#### **Protective Gloves:**

Protective gloves or Barrier cream are recommended when contact with dust or mist is likely. Prior to applying the Barrier cream or use of protective gloves, wash thoroughly.

## **Eye Protection:**

Safety glasses with side shields or goggles are recommended.

Other Protective Equipment: N/A

## SPECIAL PRECAUTIONS

## Precautions to be Taken in Handling and Storage:

Maintain good housekeeping procedures to prevent dust accumulation during grinding. Avoid dust inhalation and direct skin contact with dust.

#### **Other Precautions:**

Clean up methods which avoid dust generation such as vacuum (with appropriate filter to prevent airborne dust levels which exceed the PEL or TLV), wet dust mop, or wet clean-up. If airborne dust is generated, use an appropriate NIOSH approved respirator. Do not use coolant for wet clean up.

Wash hands thoroughly after handling, before eating or smoking. Wash exposed skin at the end of work shift. Do not shake clothing, rags, or other items to remove dust. Dust should be removed by washing or vacuuming (with appropriate filters) the clothing, rags, or other items.

Periodic medical examinations are recommended for individuals regularly exposed to dust or mist.

Although Micro 100, Inc. has attempted to provide current and accurate information herein, Micro 100, Inc. makes no representations regarding the accuracy or completeness of the information and assumes no liability for any loss, damage, injury of any kind which may result from or arise out of the use or reliance on the information by any person.